



Annual Users' Conference

**ADVANCING RADIATION SAFETY.
EMPOWERING PROGRESS.**

M Resort, Henderson, NV | June 15 – June 18



MIRION
TECHNOLOGIES

*Advancing Radiation Safety.
Empowering Progress.*

© 2026 Mirion Technologies. All rights reserved.

Troubleshooting Radiation Monitoring Systems Methods and Best Practices

Mehran Mohammadian, P.E.

Application Support Engineer

Mirion Connect | Annual Users' Conference 2026

Henderson, NV

Daily Check-In:

Tuesday



*Please take a moment
to check in for today's
session.*

Agenda



Agenda

- *Approach*
- *Basic Questions to Ask*
- *Basic Troubleshooting*
- *Examples*
- *Survey and Q&A*

Approach




RMS Troubleshooting

- *The plant is filled with a variety of RMS equipment fulfilling different roles: area monitors, containment monitors, effluent (gas or liquid) monitors, all of varying levels of complexity*
- *Not to mention:*
 - *Varying manufacturers*
 - *Varying vintages (some analog, some digital)*


Basic RMS Channel

At its core, every radiation monitor is composed of a relatively simple set of elements.



RMS Troubleshooting


What about this thing?



PING 206S


Basic RMS – Skid / System of Monitors

Still Relatively Simple



Basic RMS – Skid / System of Monitors

OK Not quite that simple, but still not too bad.



Basic Questions



Basic Questions

- *What's the problem?*
- *When did it occur?*
- *Who has interacted with the monitor recently?*
- *Is it intermittent or continuous?*
- *What conditions have changed that might affect the monitor behavior?*
 - *This doesn't necessarily mean "Is it seeing real radiation?"*

Basic Questions

What's the Problem?

- *Noise: spikes, spurious alarms, spurious faults*
- *“Dead” electronic unit (No display, no communication, relays in rest state, etc...)*
- *Faults reported by monitor*
 - *Detector related faults (Electrical test fault, Reference peak fault, low counting (or low current) fault...)*
 - *Faults related to ancillary measurements (flow rate measurement, pressure measurement, etc.)*
- *Pump stopped*
- *Etc...*
- *Sometimes obvious (e.g. “Buzzer & light fault”)*
- *Sometimes not obvious (e.g. spikes, spurious alarms)*

Basic Questions

When did it occur?

- Usually during the night shift on a weekend...
- This is where your event log and historical trends come in handy!


Events / LPU-SI - LPU SI Gam (@102)

Event types

Update Save

Type	Date	Time	Parameters	Code
Infos	06/12/1995	11:35:20	Unit in bypass mode (relay off) OFF	8001:0020
Command	06/12/1995	11:35:20	Enable/Disable the bypass mode	0078:001E
Infos	06/12/1995	11:32:38	Unit in bypass mode (relay off) ON	0001:0020
Command	06/12/1995	11:32:38	Enable/Disable the bypass mode	0078:001E
Infos	06/12/1995	11:32:38	Unit in normal operation mode ON	0001:0010
Infos	06/12/1995	11:32:38	Unit in maintenance mode OFF	8001:0040
Command	06/12/1995	11:32:34	Go to normal mode	0078:0021

Help OK



Basic Questions

Who has interacted with the monitor recently?

- *Different parties, with varying levels of familiarity with the monitor, may need to interact with the monitor:*
 - *I&C Technicians: high level of familiarity, infrequent interaction (hopefully!)*
 - *Operators: lower level of familiarity, but often frequent interactions*
 - *Chemistry: lower level of familiarity, but often frequent interactions*
 - *Interaction may be “invasive” (e.g. filter change-outs)*
 - *Interaction might not work on other equipment in vicinity of monitor?*
 - *Walkdowns?*
 - *Work may not have been directed or intended*
 - *An area where an air monitor is sampling from?*

Basic Questions

Who has interacted with the monitor recently?

- *Is it intermittent or continuous?*
- *Can it be timed/ predicted?*
- *What conditions have changed that might affect monitor behavior*
 - *Startup or shutdown*
 - *Transient condition in process being monitored?*


Basic Troubleshooting



Basic Troubleshooting

Swapping components: brute force but effective

Group of identical monitors



Step 1: convince yourself that swapping components won't damage the working monitor (i.e. short on a HV cable)


Step 2: switch cables at the electronic units and see where the problem goes

Step 3: if the problem follows the detector, switch at the other side (to rule out the cable)

Basic Troubleshooting


Swapping components: brute force but effective

Standalone monitor
(or operating monitors can't be removed from service)



Order of component replacement depends on the nature of the problem

Troubleshooting the Electronic Unit



- *N16 Monitors*
- *IM201*
- *PM205*
- *NGM 216*
- *LM 211/212*
- *SAM 20X Adjacent-to-Line Monitors*
- *Specialized Process Monitors*


Troubleshooting the Electronic Unit (Example: LPDU3/SAS)

LPDU Front Panel • LCD & board • Front panel board • Buzzer • Lights • Ethernet converter (optional)			
MA2 Board • 3.3V, 5V (digital circuits) • $\pm 15V$ (analog circuits) • 24V (lights, external sensors) • RS485 isolation • Analog output isolation • Relays	CT2 Board • Daughter board w/ • Microprocessor • Embedded S/W • Compact flash • ESD functions (DP inputs, analog inputs on LPDU top connector) • Display functions • Serial links	ASP Board (SAS & SPIPS only) • 1024 channel MCA • Spectrum storage	CM Board • Detector power (low or high voltage) • Detector signal: • Acquisition • Amplification • Digitization • Detector connection monitoring (high voltage, current, etc.)
AC/DC Power Supply Block • Filter • Fuse • Transformer • AC/DC Linear Power Supply			


Component Level Troubleshooting

- *Not as simple as it used to be.*
- *General recommendation is to replace entire circuit boards (boards can often be sent to vendor for repair)*

Instrumentation board of old:



LPDU3 microprocessor board:



.mod File Capture and Support from Mirion

- *A .mod file is a simulator file that is a snapshot of a unit and its stored data that can be viewed in MASS2 as a record of monitor operation.*
- *Captures event history for the monitor, data trends, any current status fault, and all active readings at the time of file generation.*
 - *This is an invaluable tool when seeking technical support from Mirion (RMS-Support@mirion.com) or via phone call to our RMS Support Team:
+1 770-432-2744 [Menu Option 2]*
 - *Support may ask you to generate a set of .mod files for the entire monitor group.*
 - *This can aid in diagnosing problems for a set of monitors as they can be loaded into MASS2.*

.mod File Capture and Support from Mirion


- Generating a .mod file is simple and can be performed directly through MASS2 interface as follows:
 - Select an LP(D)U or xDU of interest
 - Verify that box next to device has check next to it:

The screenshot displays the MASS2 interface for device selection and monitoring. On the left, a tree view shows the hierarchy: a parent box labeled 'RAD-6304' with an unchecked checkbox, which branches into two child boxes: '6304-L' (checked checkbox) and '6304-H' (unchecked checkbox). Both child boxes have a green 'Ok' button next to them. To the right of this tree is a table of monitoring parameters, each with an unchecked checkbox and a green value field.

☐	NG Rel	0 $\mu\text{Ci/s}$
☐	NGMActC	0 $\mu\text{Ci/cc}$
☐	NG CPM	20.12 CPM
☐	FlowRate	1.9638 SCFM
☐	Release	3.284e+04 $\mu\text{Ci/s}$
☐	NG Act	8.821e-04 $\mu\text{Ci/cc}$
☐	FlowRate	1.0414 SCFM

.mod File Capture and Support from Mirion


- At the top menu of MASS2, select "Tools" followed by "Ramdebug", which opens the following window:



.mod File Capture and Support from Mirion

- *Define the location to save the simulator file.*
- *Select "Valid"*
- *Once the file has been created, an "End of Debug" dialog box will appear.*
- *Resulting file will be saved with ".mod" extension. This file can be viewed later in MASS2 by the user or it can be sent to Mirion for technical support.*
- *Creating and viewing a simulator file will be discussed at a Thursday MASS2 Breakout session.*

Examples



Examples

- *Spikes on monitor with scintillation detector (high voltage)*
 - *Liquid monitor spikes, false alarms: intrusion of saltwater mist into detector connector (detector assembly on turbine deck, seaside plant)*
 - *N16 monitor spikes, false alarms: connector damaged (kicked) by workers on another job*
 - *Control room airborne monitor spikes, false alarms: pipe radiography being performed nearby (i.e. the spikes were real!)*
 - *ATL liquid monitor spikes, false alarms, temperature faults: detector installed in a well, the well flooded. Temperature faults caused by HV short to temperature wire.*

Examples

- *RS485 communication failures on containment monitor*
 - *Monitor functioned normally during commissioning*
 - *Intermittent communication failures between the control room (RDU3) and skid (LPDU3) appeared during reactor startup*
 - *Failures became progressively worse and eventually constant*
 - *RS485 was run on the cores of 2 coaxial cables (Westinghouse composite cable)*
 - *Switching to the core and shield of 1 coaxial cable resolved the problem*
 - *Cause of problem never really determined.*

Examples

- *Intermittent spikes on particulate monitor (silicon detector, low voltage)*
 - *Monitor functioned normally during commissioning*
 - *Intermittent spikes and false alarms appeared following a brief period of operation.*
 - *Replacing the detector appeared to solve the problem, but the spikes soon returned*
 - *Replacing the electronic unit (LPU) did not resolve the problems*
 - *Monitor was heat traced close to the detector temperature limit- possible temperature induced noise?*
 - *Detector was removed from service → not noisy in bench testing*
 - *Heating the detector to check for noise yielded an unexpected result- liquid water weeping from the detector!*
 - ✓ *Water + electronics = spikes*

Examples

- *Erratic Count Rate Spikes on Plastic Scintillation Detector*
 - *Customer reported that condenser air ejector monitoring system exhibited erratic count rate spikes on the LPDU and Plant Computer*
 - *On-site testing performed by Mirion personnel confirmed detector and LPDU were functioning properly; cable length alone (~320 ft) was ruled out*
 - *Introducing the current service cable within its conduit run caused background noise to jump from ~2 cps to ~1000 cps – encroaching into Window 1*
 - *Root cause: EMI and/or vibration induced by cable's routing environment near turbine deck equipment (cable was routed nearby a 440V generator).*
 - *Conclusion: EMI noise from the plant field environment cannot be fully anticipated or mitigated by Mirion – cable routing, shielding, and EMI evaluation must be addressed during the design phase and/or with site-specific knowledge.*

Survey and Q&A



Survey for:

Instrumentation and Control (I&C) Forum



*Please take a moment
to fill out a short survey
on this session.*

Thank you

